

Kodak i600 Series Scanners Software Release Notes

Version CD 4.4 Summary

Purpose of Release: This release was created to correct a problem with the ISIS driver not setting the elevator mode correctly and to update the TWAIN driver to the version 9.x level.

Note: On 5/16/2008 Kofax released an update to their VirtualReScan(VRS) v4.2 product to enable support of this version (9.x) of the Kodak TWAIN driver. All Kofax VRS customers must have VRS 4.2 and the *Kodaki600Update.exe* update installed to successfully use this driver.

Date: January 10th, 2008

Versions:

TWAIN driver:	9.25.5
ISIS driver:	2.0.10711.12001
Scan Validation Tool:	6.10
Firmware:	4.03
STI driver:	1.3 (signed)
Color Tables:	2.0.4

New Features from CD 4.2:

1. (none)

Improvements from CD 4.2:

1. ISIS: Corrected problem with elevator not descending.
2. ISIS: Corrected multifeed detection by length configuration problem.
3. ISIS: Corrected rear camera configuration issues.
4. TWAIN: Corrected problem with running driver on a Czechoslovakian Windows PC.