

Kodak i700 Series Scanners Software Release Notes

Version CD 1.13 Summary

Purpose of Release: This release was created to enable new scanner features for elevator speed improvements. Several scanner firmware issues were also addressed in this release. (See Release notes for i700 Scanner Firmware version 2.1.3 for more information). All feature changes were made through the i700 Scanner firmware version 2.1.3 and do not require any updates to the host PCs TWAIN or ISIS drivers. (Please note that firmware 2.1.3 or greater must be installed to enable new features).

There are no changes to the TWAIN driver or the ISIS driver in this release. No new features were added to the TWAIN or ISIS drivers.

Customers may choose to only install the new scanner firmware v2.1.3 to enable the new i700 scanner features without installing the InstallSoftware_i700_v1.13.exe driver installer.

Date: April 16th, 2009

Versions:

TWAIN driver:	9.49
TWAIN ui:	3.22 (help 1.1)
ISIS driver:	2.0.10809.29001
Scan Validation Tool:	6.12
Firmware:	2.1.3
STI driver:	1.2 (wiascnr 2.24)
Color Tables:	1.0

New Features from CD 1.12:

1. (none).

Improvements from CD 1.12:

1. The User Manual was updated to include new scanner features.
2. Setup: Improved Web Installer to no longer be dependent on autorun.inf to prevent "Operating System not supported" messages during installation.

Known Issues:

1. (none)

Version CD 1.12 Summary

Purpose of Release: This release was created to add support for the new Kodak 730 and Kodak i750 scanners.

Date: February 9th, 2009

Versions:

TWAIN driver:	9.49
ISIS driver:	2.0.10809.29001
Scan Validation Tool:	6.12
Firmware:	2.0.21
STI driver:	1.2 (wiascnr 2.24)
Color Tables:	1.0

New Features from CD 1.4:

2. Support for i730 and i750 models.

Improvements from CD 1.4:

1. ISIS#3020 – Corrected problem with some options under 'Blank Image Detection' not being saved for Back side Image.
2. ISIS#3019 – Corrected problem with the back side blank image being deleted when 'Blank Image Detection' enabled for Front Image #1 image only.
3. ISIS – Corrected problem with detecting scanner in Citrix environment.
4. PR#12261- Scanner firewire now able to disconnect and reconnect properly.
5. CR#1885 - Many updates to TWAIN GUI text in Japanese.

ISIS only driver update

ISIS Driver Version eki700_2.0.10807.28001 Summary

Date: July 28, 2008

New Features from version 2.0.10711.12001:

3. (none)

Improvements from version 2.0.10711.12001:

4. ISIS#2943-Imprinter Date format can't be changed from "DDD" to "YYYYDDD"
5. ISIS#2944-Imprinter Date Format function is disabled when type "%Y" in Format Template and then delete it
6. PR#12051 and PR#11669-The Julian Date print strings (%2Y %3Y %4Y %5Y) are not functional or available in the driver
7. ISIS#2600-Contrast Setting does not persist
8. ISIS-2552- [German Interface only] has issues with multistream settings (border removal works for 1st stream not for second)

Version CD 1.4 Summary

Purpose of Release: Initial release of the i700 drivers and firmware. This release only supported the i780 scanner and should not be used with a Kodak i730 or Kodak i750 scanner.

Date: January 11th, 2008

Versions:

TWAIN driver:	9.25.5
ISIS driver:	2.0.10712.11001
Scan Validation Tool:	6.10
Firmware:	2.0.6
STI driver:	1.2 (signed)
Color Tables:	1.0